Attachment A: Photo Log Lawson Road



DSCN3373 – Pile of crushed glass



DSCN3374 – Piles of dirt and pooled stormwater



DSCN3376 – Piles of dirt with pooled stormwater



DSCN3377 – Piles of dirt and sand with pooled stormwater



DSCN3378 – Pile of vegetative debris



DSCN3382 – Back of property vegetation and berm



DSCN3383 – Back of property vegetation and berm



DSCN3384 – Back of property




DSCN3385 – Ponding at the back of the property




DSCN3386 – Ponding at the back of property



DSCN3390 – Stormwater ponded on property



DSCN3391 – DNREC permit for portable crusher



DSCN3398 – Sussex County letter on portable crusher



DSCN3399 – Pile of vegetative debris